-		* ;		(
Sl. No.	Items of work	Unit	Rates estimated.	Quantity	Rates to be quoted
			Cistination.	****	quotou
			Rs. a. p.		Rs.
4 5	Burnt brick in lime "mortar Burnt stone slabs 5 to 6" thick one line dressed	C.ft.	0 4 0	5,472	
	for exposed faces and fixed in lime mortar (old				
	burnt stone slabs availabel at site)	S.ft.	0 2 0	928	
6	Providing trusses and fixing including painting, etc., as per Marin's specifications 10' from		-		
. 7	centre to centre	Cwt.	16 0 0	66	
7	oiling	C.ft.	5 0 0	389	
8	Roofing with 1st Class Mangalore pattern tiles on	Oile.	0 0 0	909	2 2
	teak wood reapers 2"×1"	Sqr.	22 0 0	59.84	1
9	Teakwood doors frames 4" × 5" with panelled				4
	shutters 14" thick folding doors with hinges,				
200	bolts, painting, etc., complete	S.ft.	1 12 0	68	
9a	Providing and fixing teak wood doors frames				
	$3\frac{1}{2}'' \times 4''$ panelled shutters $1\frac{1}{4}''$ thick with hinges, bolts painting, etc., complete	-	1 8 0	77	
10	Teakwood windows with frames 3"×4" with iron	"))	1 0 0	''	1 11
10	bars 3" dia. 41" e to e with glazed shutters			5.	
	hinges, etc., complete, expanded metal fixed	0.00		-	
	inside, painting, etc., complete	,,	2 0 0	288	
11	Chunam plastering	Sqr.	3 0 0	80.05	4
11a	White washing 2 coats	22	0 4 0	80.05	
.12	Flooring with burnt stone slabs over 3" lime mortar	0	90 0 0	39.00	
13	quoin dressing and fixed	Sqr. R.ft.	20 0 0	84	17.2
14	Teakwood eave board from 12" to 9" wide 3" thick	10,10,	U 0. U	, 01	
, 11	including painting	"	0 8 0	360	
15	Mangalore ridge tiles set in mortar	,,	0.70	136	
16	Cement pointing to basement	Sqr.	3 0 0	6.64	
17	Drilling holes in slabs for fixing girders	Each	0 4 0	54	
18	Providing and fixing R.C. ventilators	Sq.ft.	1 0 0	12	
19	Fixing R. S. Tatas tested girders above big doors			1	
	including hoisting fixing and painting 6"×3" at 12 lbs.	Cwt.	14 0 0	2.14	
20	Boxing girders with terrace brick in cement mortar	Rift.	0, 6, 0	10 -	
21	Constructing steps in front of doors with available				
-	labs	L.S.			20
22	Dismantling old mantapam design building now	1 , .			3
	need as lumber Stores Shed as per details below:				
	(a) Removing parapet wall $1\frac{1}{4} \times 1\frac{1}{8}$ of burnt brick in	R.ft.	0 0 4	290	, '
	in mortar including coping (b) Removing burnt stone slab roofing with	Thatta	0 0 ±	400	P + 1
	cement and stacking at places	Sqr.	3 0 0	26.04	
-	(c) Removing beams 1'×1'×6'	Each	0 8 0	60	
	(d) Removing vertical pillars (11½' high) and				4.5
	stacking	117	0 8 0	40	
	(e) Removing capitals	72	0 4 0	40	
	(f) Removing size stone in mortar and removing	O.L.		E 10E	
	debris	C.ft. Sqr.	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	5,195 2,301	
23	(g) Removing burnt stone slab flooring Old size stone in lime mortar	C.ft.	0 2 6	2,924	
40	Old olde Blotte id mine morest				
•					_

B. R. GARUDACHAR, Executive Engineer.

MANDYA DIVISION.

Abstract Notification dated 16th December 1938.

The attention of the public is hereby invited to the Advertisement, published in pages 2267-2271 of the issue, dated 22nd December 1938 in Mysore Gazette, calling for renders for constructing District Hospital at Mandya.

The last date of receipt of tender is up to 12 noon on 9th January 1939.